




1. DESIGN HAS 198 TRACE ERRORS DUE TO TRACE KEEPOUTS FOR J38-J41 ON PLANE LAYERS
2. AREA FILLS WERE RESTRUCTURED WITH .015 CLEARANCE FOR 'PWR025' NET TYPE. THAN RESET CLEARANCE BACK TO .007

MVD-3 001 10Y-226258M05 11-10-98
COMPONENT SIDE SILKSCREEN